



Style#
371



EMBROIDERY TEAR AWAY

Fuse-N-Tear™

TEAR-AWAY EMBROIDERY STABILIZER

Fuse-N-Tear™ easily adds body and support during stitching. Simply iron Fuse-N-Tear™ to fabric and when completed, tear away excess stabilizer. Fuse-N-Tear™ leaves no sticky residue after removal.

GENERAL DIRECTIONS:

- Use 1 to 3 layers of Fuse-N-Tear™ depending on the weight of your fabric and the density of your embroidery design. When using multiple layers, fuse one at a time.

1. Secure Fuse-N-Tear™ to wrong side of fabric by ironing the smooth side down with a dry iron at your fabric's suggested temperature. Press for 5-10 seconds and check to see if fusing is complete. If needed, add a little more time. Repeat if adding multiple layers.




2. Allow to cool
3. Stitch desired area.
4. Upon completion of stitching, gently trim or tear away excess Fuse-N-Tear™.



Free projects using this and other Pellon® products at www.PellonProjects.com or call 1-800-223-5275.



PELLON PROJECTS:



Project: Checkbook Cover
Designer: Alexandra Henry
Level: Intermediate

Two pockets hold the checks and the register. One flap makes it easy to write carbon checks. Get the complete pattern at www.PellonProjects.com

ADDITIONAL PROJECT IDEAS:

Use Fuse-N-Tear™ for projects in:

- **Apparel:** Decorative stitching, appliqués and monogramming.

Fiber Content:

70% Polyester / 30% Cellulose, Acid Free

Care Instructions:

Machine wash warm or dry clean.

For more information go to www.pelloninstructions.com



Serie#
371



BORDADOS REMOVIBLES

Fuse-N-Tear™

ESTABILIZADOR REMOVIBLES DE BORDADO

Fuse-N-Tear™ agrega soporte y da forma durante el bordado. Plancha Fuse-N-Tear™ en la tela y cuando termine, jale el exceso del estabilizador. Fuse-N-Tear™ no dejará marcas después de ser removido.

DIRECCIONES DE USO:

- Dependiendo del peso de la tela y la densidad del bordado, utilice 1 a 3 capas de Fuse-N-Tear™. Al utilizar varias capas, fusione una a una.

1. Para asegurar Fuse-N-Tear™ a la tela, planche por la parte suave 1 - 3 capas juntas por el revés de la tela a una temperatura que la tela resista. Presione de 5-10 segundos y verifique si se han fusionado. De ser necesario presione por mas tiempo. Al utilizar varias capas, repita este paso.



2. Deje enfriar
3. Zurza área deseada.
4. Jale o corte el exceso de Fuse-N-Tear™ una vez terminado el bordado.




Para mayor información visite www.pelloninstructions.com

Para proyectos gratis de este y otros productos de Pellon® visite www.PellonProjects.com o llame al 1-800-223-5275.



PELLON PROJECTS:



Proyecto: Porta Chequera
Diseñadora: Alexandra Henry
Nivel: Intermedio

Doble bolsillo para guardar la chequera y el registro de cheques. Una solapa hace fácil el escribir cheques con copia carbón. Obtenga este patrón en www.PellonProjects.com

MAS IDEAS PARA PROYECTOS:

Utilice Fuse-N-Tear™ en proyectos para:

- **Accesorios:** Remallados, ojales, bordados decorativos y aplicaciones.

Contenido de Fibra:

70% Polyester / 30% Cellulose, Acid Free

Instrucciones de Mantenimiento:

Lave a máquina en temperatura media o lave en seco.